

VEHICLE INSPECTION REPORT

YG22NVC

Ford Transit 350 2.0 EcoBlue 130ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 17/05/2022

Year 2022

Mileage 73,277 Miles Warranted

Fuel Type Diesel

Colour SILVER

VIN WF0EXXTTRENL09239

Body Style Panel Van L3

Keys 2

CAP Clean £10,300.00

CAP Average £9,550.00

CAP Below £8,225.00

Gearbox MANUAL

Gears 6

Doors 2

Steering Combi Standard Axle

Rear Suspension Steel

3 REAR SEATS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Bluetooth connection
- Metallic Paint
- Rear parking sensor
- Drivers airbag
- Radio/CD
- Cloth seat trim
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Door osf
Dented
Over 30mm



3: Qtr Panel osr
Dented
Over 30mm



4: Tailgate
Dented
Over 30mm



5: Door nsr
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
Over 30mm



7: Flasher Side Repeater ns
Broken
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK