

VEHICLE INSPECTION REPORT

DK17KYS

Man TGM 18 250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	24/04/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMAN08ZZ7HY357083	Gearbox	MANUAL
Mileage	246,042 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/11/2025	Rear Suspension	Steel

MOT HISTORY INCORRECTLY RECORDED IN MILES/KM HMF 1420K REMOTE CRANE (YEAR 2016)

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Central locking
- Park assist camera
- Cloth seat trim
- Digital radio
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Cracked
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Door nsf
Dented
Over 30mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Lamp osr
Broken
Replace



7: Wing osf
Scratched
Over 25mm Thru Paint



8: Door osf
Scratched
Over 25mm Thru Paint



9: Panel Front
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		