

VEHICLE INSPECTION REPORT

NY18GXR

Peugeot Partner 850 1.6 BLUE HDI 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 20/08/2018

Year 2018

Mileage 114,397 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF37DBHY6JJ767802

Body Style Panel Van L1

MOT Due 16/07/2026

CAP Clean £2,650.00

CAP Average £2,275.00

CAP Below £1,775.00

Gearbox MANUAL

Gears 5

AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Digital radio
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
UpTo 10mm



3: Door nsr
Dented
With Paint Damage



4: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



5: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK