

## VEHICLE INSPECTION REPORT

**NU69RZW**

### Peugeot Partner 1000 1.5 BLUE HDI 100PS

**Non Runner**

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 18/11/2019

Year 2019

Mileage 84,215 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VR3EFYHYCKJ801029

Body Style Panel Van SWB

MOT Due Expired

CAP Clean £4,800.00

CAP Average £4,225.00

CAP Below £3,375.00

Gearbox MANUAL

Gears 5

\*NON RUNNER, CRANKS BUT WILL NOT FIRE\* SIDE LOADING DOOR, E/MIRRORS

#### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Rear parking sensor
- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Front TowEye Cvr  
Missing  
Replace



2: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



3: Wing nsf  
 Scratched  
 UpTo 25mm Thru Paint



4: Door nsf  
 Dented  
 Between 10mm + 30mm



5: Door Moulding nsf  
 Scuffed (Unpainted)  
 UpTo 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	Fault		