

VEHICLE INSPECTION REPORT

NA65UJC

Scania P 250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	07/01/2016	VIN	YS2P4X20005407700	Axle Combi	4x2
Year	2016	Body Style	Fridge Box	Rear Suspension	Air
Mileage	801,604 Km Warranted	MOT Due	30/11/2025	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column
Colour	WHITE	Gearbox	AUTOMATIC		

MOT HISTORY INCORRECTLY RECORDED IN MILES/KM THERMOKING T1000R UNIT

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- USB/iPod interface
- Air conditioning
- Front electric windows
- Drivers airbag
- Partial leather seat trim


Photos







Condition Check



Damage Photos



1: Headlamp ns
Broken
Replace



2: Moulding nsf Wing
Broken
Replace



3: Door osf
Dented
Over 30mm



4: Door osf
Chipped
Edge Chip



5: Door osf
Chipped
Edge Chip



6: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



7: Door osf
Chipped
Over 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	