

VEHICLE INSPECTION REPORT

YC69HNJ

Daf CF 410

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/10/2019

Year 2019

Mileage 173,061 Km Not Warranted

Fuel Type Diesel

Colour White

VIN XLRADM4100G268374

Body Style Tipper Grab

MOT Due 30/06/2025

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

PALFINGER EPSILON M125L (YEAR 2019)

Tyres

NSF NSI1

NSI2 NSI3

NSI4

OSF OSI1

OSI2 OSI3

OSI4

Spare NSO1

NSO2 NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Door nsf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -