

VEHICLE INSPECTION REPORT

SN11BJU

MERCEDES-BENZ SPRINTER 313 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

| | | | | | |
|-----------|---------------------------|-------------|-------------|-----------------|---------------|
| Reg. date | 11/07/2011 | Body Style | Welfare Van | Gearbox | MANUAL |
| Year | 2011 | Keys | 1 | Gears | 6 |
| Mileage | 65,498 Miles Warranted | MOT Due | Expired | Doors | 2 |
| Fuel Type | Diesel | CAP Clean | £2,075.00 | Steering Combi | Standard Axle |
| Colour | WHITE | CAP Average | £1,625.00 | Rear Suspension | Steel |
| VIN | WDB9066332S552207 | CAP Below | £1,075.00 | | |

* WARNING LIGHT ON DASH * REAR SEATS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Bonnet
Rusted
Over 5mm



4: Wing osf
Rusted
Over 5mm



5: Door osf
Dented
Over 30mm



6: Qtr Panel osr
Rusted
Over 5mm



7: B Post os
Rusted
Over 5mm



8: Tailgate
Dented
With Paint Damage



9: Qtr Panel nsr
Rusted
Over 5mm



10: Sill ns
Rusted
Over 5mm



11: Door nsf
Dented
With Paint Damage



12: Wing nsf
Dented
With Paint Damage



13: Roof
Rusted
Over 5mm

Interior

| Carpet Condition | | Average | Upholstery Condition | | Average |
|--------------------------|--|---------|--|--|---------|
| Seat Condition | | Poor | Odour | | No |
| Engine Runs | | OK | Gearbox 1st and Reverse Test | | OK |
| Brakes | | OK | Clutch Slip Test from Static | | OK |
| Turbo Boosting | | OK | Gearbox Static Gear Selection (engine running) | | OK |
| Parking Brake | | OK | No Excessive Smoking | | OK |
| EML light illuminated | | OK | Oil warning light illuminated | | OK |
| Airbag light illuminated | | OK | DPF light illuminated | | OK |
| ABS light illuminated | | OK | Service indicator light illuminated | | Fault |
| Windows | | OK | Radio | | OK |
| | | | Steering | | OK |