

# VEHICLE INSPECTION REPORT

**C356035**

## DON BUR BOX

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |             |            |                   |                 |            |
|-----------|-------------|------------|-------------------|-----------------|------------|
| Reg. date | 01/01/2013  | VIN        | SEPBV38GKDL061900 | Steering Combi  | Front Lift |
| Year      | 2013        | Body Style | Trailer           | Rear Suspension | Air        |
| Mileage   | Not Showing | MOT Due    | 30/06/2026        | Rear Doors      | Roller     |
| Fuel Type |             | Brakes     | Disc              |                 |            |
| Colour    | RED         | Axle Combi | Tri               |                 |            |

\*CORROSION\* BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos









