

VEHICLE INSPECTION REPORT

58200

STIHL

Inspection

Vehicle

VAT	Plus VAT
V5	Not Present

Details

Reg. date	Mileage	TBC	Colour
Year	Fuel Type		VIN

PETROL MOWER *FOR SPARE OR REPAIR - DOES NOT PULL* NO PLATES

Tyres

NSF
NSR
OSF
OSR
Spare

Photos

