

VEHICLE INSPECTION REPORT

580431

HONDA HRX537 C4HYEA

Inspection

Vehicle

VAT	Plus VAT
V5	Not Present

Details

Reg. date	Mileage	TBC	Colour
Year	Fuel Type	VIN	MAGA2580431

MOWER, HONDA GCV 190 PETROL ENGINE *FOR SPARE OR REPAIR - DOES NOT PULL, NO HANDLE OR FRONT WHEELS*

Tyres

NSF
NSR
OSF
OSR
Spare

Photos

