

VEHICLE INSPECTION REPORT

127890

HONDA HRX537 C5HYE

Inspection

Vehicle

VAT	Plus VAT
V5	Not Present

Details

Reg. date	Mileage	TBC	Colour
Year	Fuel Type		VIN
2019			MAMA1127890

MOWER, HONDA GCVX 200 PETROL ENGINE *FOR SPARE OR REPAIR - DOES NOT PULL, ENGINE CORROSION*

Tyres

NSF
NSR
OSF
OSR
Spare

Photos

