

VEHICLE INSPECTION REPORT

018158

HONDA HRX537 C6HYEA

Inspection

Vehicle

VAT	Plus VAT
V5	Not Present

Details

Reg. date	Mileage	TBC	Colour
Year	Fuel Type		VIN
			MCGF1018158

MOWER, HONDA GCVX 200 PETROL ENGINE *FOR SPARE OR REPAIR - DOES NOT PULL*

Tyres

NSF
NSR
OSF
OSR
Spare

Photos

