

VEHICLE INSPECTION REPORT

Vehicle

FN64DCO

DAF CF 330

Inspection

		VAI	I IUS VAI		
		V5	Buyer To Apply		
Details					
Reg. date	24/10/2014	VIN	XLRASM4100G033947	Axle Combi	6x2
Year	2014	Body Style	Dropside & Crane	Steering Combi	Rear-Lift Steer
Mileage	248,401 Km Not Warranted	MOT Due	Expired	Rear Suspension	Air
		Cab Type	DAY CAB		
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	WHITE				

Plus VAT

MOT HISTORY INCORRECTLY RECORDED IN MILES/KM, WARNING LIGHTS ON DASH HMF 1720 (2 EXT) REMOTE CRANE

Tyres			
Tyres NSF			
NSR			
OSF	,		
OSR			
Spare			

Features

Navigation system

• Digital radio

• Air conditioning

Photos









