

# VEHICLE INSPECTION REPORT

**YA21ZGL**

## Seat Arona 1.0 TSI SE Technology

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

### Details

Reg. date 28/05/2021

Year 2021

Mileage 41,249 Miles Not Warranted

Fuel Type Petrol

Colour WHITE

VIN VSSZZZKJZMR122700

Body Style Hatchback

MOT Due 21/01/2026

CAP Clean £8,975.00

CAP Average £7,950.00

CAP Below £6,925.00

Gearbox MANUAL

Gears 5

Doors 5

ALLOY WHEELS, E/MIRRORS

### Tyres

NSF

NSR

OSF

OSR


Spare

## Features

- Navigation system
- Rear parking sensor
- Air conditioning
- Front electric windows


## Photos







Condition Check



Damage Photos



1: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



2: Wheel osf  
Scratched  
Over 50mm

Interior

Carpet Condition            OK  
Seat Condition              OK

Upholstery Condition      OK  
Odour                         No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK