

VEHICLE INSPECTION REPORT

217789

HONDA HRX537 C5HYE

Inspection

Vehicle

| | |
|-----|-------------|
| VAT | Plus VAT |
| V5 | Not Present |

Details

| | | | |
|-----------|-----------|-----|-------------|
| Reg. date | Mileage | TBC | Colour |
| Year | Fuel Type | | VIN |
| 2020 | | | MAMA1217789 |

MOWER, HONDA GCVX 200 PETROL ENGINE *PULLS DOES NOT START*

Tyres

| |
|-------|
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Photos

