

VEHICLE INSPECTION REPORT

DK17KYT

Man Tg-M 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	12/05/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMAN08ZZ8HY355522	Gearbox	MANUAL
Mileage	302,849 Km Warranted	Body Style	Flatbed & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/05/2026	Rear Suspension	Steel

MOT HISTORY INCORRECTLY RECORDED IN MIKLES/KM SERVICE SCHEDULE AVAILABLE, HMF 1420 K2 (2 EXT) REMOTE CRANE (YEAR 2016)

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Scratched
Over 25mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wing osf
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osf
Dented
Over 30mm



8: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		