

VEHICLE INSPECTION REPORT

FN20AYE

Daf CF 290

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	02/04/2020	VIN	XLRAEM3700G293615	Cab Type	SLEEPER CAB
Year	2020	Body Style	Flatbed	Gearbox	AUTOMATIC
Mileage	317,823 Km Warranted	CAP Clean	£18,400.00	Axle Combi	4x2
Fuel Type	Diesel	CAP Average	£17,450.00		
Colour	BLUE	CAP Below	£15,100.00		

WARNING LIGHT ON DASH SLIDING CANOPY, SURROUND CAMERA SYSTEM, ADVANCED EMERGENCY BRAKING SYSTEM, LANE KEEP ASSIST

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Navigation system
- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Other
N/A
N/A



3: Bumper Front
Chipped
Multiple Chips



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Chipped
Multiple Chips



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Other
N/A
N/A



8: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



9: Other
N/A
N/A

10: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	