

VEHICLE INSPECTION REPORT

PHH122P

VOLVO G88

Imported

Inspection

Vehicle

VAT	Margin
V5	To Follow

Details

Reg. date	31/12/1976	Colour	SILVER	Gearbox	MANUAL
Year	1976	VIN	47157	Axle Combi	8x4
Mileage	905,819 Km Not Warranted	Body Style	Flatbed		
Fuel Type	Diesel	Cab Type	SLEEPER CAB		

DIFFS & GEARBOX HAVE BEEN RECONDITIONED, CAB INTERIOR RESTORED TO ORIGINAL CONDITION, 16 SPEED GEARBOX.

Tyres

NSF
NSR
OSF
OSR
Spare