

VEHICLE INSPECTION REPORT

C351519

DON BUR

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	Colour	RED	Axle Combi	Tri
Year	2013	VIN		Steering Combi	Front Lift
Mileage	Not Showing	Body Style	Trailer	Rear Suspension	Air
Fuel Type		Brakes	Disc	Rear Doors	Roller

CORROSION BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



