

VEHICLE INSPECTION REPORT

C356013

DON BUR FRIDGE BOX 3335153

Inspection

Vehicle

VAT

V5 N/A

Details

Reg. date	01/01/2013	Colour	RED	Brakes	Disc
Year	2013	VIN	SEPBV38GKDL061878	Axle Combi	Tri
Mileage	Not Showing	Body Style	Trailer	Rear Suspension	Air
Fuel Type		MOT Due	31/05/2026	Rear Doors	Roller

CORROSION BPW AXLES, FRONT LIFT, RAISE AND LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare