

VEHICLE INSPECTION REPORT

BU68YYV

Ford Transit 350 2.0 TDCI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 20/11/2018

Year 2018

Mileage 154,115 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0EXXTTGEJJ15507

Body Style Tipper Double Cab

MOT Due 28/11/2025

CAP Clean £5,925.00

CAP Average £5,125.00

CAP Below £4,000.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH AD-BLUE, WEIGH SYSTEM, TOW BAR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Roof
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Chipped
Multiple Chips




8: Door Moulding nsr
Missing
Replace



9: Bumper Rear
Dented
Over 30mm



10: Bumper Front
Scratched
Over 100mm Thru Paint



11: Screen Front
Chipped
Over 10mm



12: Screen Front
Scratched
Over 30mm



13: Door Pad nsr
Broken
Replace



14: Seat Back Cover nsr
Soiled
Heavy



15: Seat Base Cover nsr
Soiled
Heavy



16: Seat Back Cover osr
Soiled
Heavy




17: Seat Base Cover osr
Soiled
Heavy



18: Door Pad osr
Broken
Replace



19: Seat Base Cover osf
Holed
Over 3mm



20: Seat Base Cover nsf
Soiled
Heavy



21: Seat Base Cover nsf
Soiled
Heavy



22: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		OK	Upholstery Condition		Poor
Seat Condition		Poor	Odour		No
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	Fault				