

# VEHICLE INSPECTION REPORT

**YR69GDU**

## Ford Transit Connect 240 1.5 ECOBLUE 100PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 19/12/2019

Year 2019

Mileage 69,852 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0SXXWPGSKU88837

Body Style Panel Van L2

MOT Due 18/12/2025

CAP Clean £5,525.00

CAP Average £4,850.00

CAP Below £3,875.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Digital radio
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Panel Front  
Scratched  
Over 25mm Thru Paint





3: Wing nsf  
Dented  
With Paint Damage




4: Qtr Panel nsr  
Dented  
Over 30mm



5: Qtr Panel nsr  
Dented  
With Paint Damage



6: Bumper Rear  
Scratched  
Over 100mm Thru Paint



7: Fascia Panel  
Broken  
Replace

**Interior**

**Carpet Condition** OK  
Commercial Vehicle Auctions Limited

**Upholstery Condition** Poor

Seat Condition		OK	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			