

# VEHICLE INSPECTION REPORT

**YF18UAK**

## Mercedes-Benz Citan 109 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 31/07/2018

Year 2018

Mileage 103,587 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WDF4156032U251258

Body Style Panel Van LWB

MOT Due 09/01/2026

CAP Clean £2,950.00

CAP Average £2,525.00

CAP Below £1,975.00

Gearbox MANUAL

SIDE LOAD DOOR, E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking

## Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Rear  
Dented  
Over 30mm



3: Screen Front  
Chipped  
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		