

VEHICLE INSPECTION REPORT

FA190FP

Daf LF 180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	19/08/2019	Body Style	Curtainside	Gearbox	AUTOMATIC
Year	2019	MOT Due	30/11/2025	Axle Combi	4x2
Mileage	276,137 Km Warranted	CAP Clean	£12,750.00	Rear Suspension	Steel
Fuel Type	Diesel	CAP Average	£12,000.00	Rear Doors	Barn
Colour	WHITE	CAP Below	£10,300.00	Tail Lift	Tuckaway
VIN	XLRAEL1500L486316	Cab Type	HIGH ROOF SLEEPER CAB		


ADVANCED EMERGENCY BRAKING, LANE KEEP ASSIST

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Screen Front
Chipped
UpTo 10mm



4: Door Mirror Assy nsf
Broken
Replace



5: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK