

VEHICLE INSPECTION REPORT

LF70RYY

Peugeot Partner 650 1.5 BLUEHDI 75PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/09/2020

Year 2020

Mileage 126,130 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VR3EFYHWCLJ795999

Body Style Panel Van

MOT Due 24/09/2025

CAP Clean £3,675.00

CAP Average £3,275.00

CAP Below £2,675.00

Gearbox MANUAL

Gears 5

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS, ROOF RACK

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Bluetooth connection
- Rear parking sensor
- Drivers airbag
- Cruise control
- Digital radio
- Central locking
- Navigation system
- Air conditioning
- Cloth seat trim
- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Door nsf
Chipped
Edge Chip



3: Door osr
Dented
With Paint Damage

4: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK