

VEHICLE INSPECTION REPORT

CU65DXY

Ford Transit 350 2.2 TDCI 155PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 01/02/2016

Year 2016

Mileage 95,534 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGXFM07394

Body Style Panel Van L2

MOT Due 07/01/2026

CAP Clean £3,375.00

CAP Average £2,800.00

CAP Below £2,075.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, TOW BAR, DEADLOCKS (WITH KEYS), POWER INVERTER, 240V SOCKETS

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Condition Check



Damage Photos



1: Door Pad osf
Soiled
Heavy



2: Seat Base Cover osf
Soiled
Heavy



3: Seat Base Cover nsf
Soiled
Heavy



4: Door Pad nsf
Soiled
Heavy



5: Number Plate Front
Broken
Replace



6: Panel Front
Scratched
Over 25mm Thru Paint



7: Panel Front
Scratched
Over 25mm Thru Paint



8: Bumper Front
Dented
Over 30mm



9: Wing Front Arch Extension ns
Broken
Replace



10: Door Moulding nsf
Missing
Replace



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



12: Qtr Panel nsr
Dented
Over 30mm



13: Door osr
Dented
With Paint Damage



14: Qtr Panel osr
Dented
With Paint Damage



15: Qtr Panel osr
Dented
With Paint Damage



16: Qtr Panel osr
Dented
Over 30mm



17: Door Mirror Glass os
Missing
Replace



18: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

Poor
No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		