

VEHICLE INSPECTION REPORT

CU15CZZ

Ford Transit 350 2.2 TDCI 155PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 08/06/2015

Year 2015

Mileage 115,117 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGXFK01944

Body Style Panel Van L3

MOT Due 05/05/2026

CAP Clean £2,950.00

CAP Average £2,425.00

CAP Below £1,750.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH SIDE LOAD DOOR, TOW BAR, E/ MIRRORS, HEATED WINDSCREEN, DEADLOCKS (WITH KEYS), POWER INVERTER, 240V SOCKETS

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Digital radio
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Scratched
Over 25mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Dented
Over 30mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




6: Qtr Panel nsr
Dented
Over 30mm




7: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Door osr
Dented
Over 30mm



10: Door osr
Dented
Over 30mm



11: Door nsr
Dented
Over 30mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door Mirror Assy osf
Broken
Replace



15: Door Pad osf
Soiled
Heavy



16: Carpets Front
Holed
Over 3mm



17: Seat Base Cover nsf
Soiled
Heavy



18: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition
Seat Condition

Poor
Poor

Upholstery Condition
Odour

Poor
No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault