

VEHICLE INSPECTION REPORT

NJ19BDE

MERCEDES-BENZ ACTROS 2545

Cat: B

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply

Details

Reg. date	29/06/2019	VIN	WDB96342320357666	Axle Combi	6x2
Year	2019	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	908,777 Km Not Warranted	MOT Due	Expired	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	STREAMSPACE CAB (2.5M, FLAT FLOOR)		
Colour	WHITE	Gearbox	AUTOMATIC		

*Category B Insurance Loss. Bodyshell Should Have Been Crushed Vehicle Should Not Be On The Road.
Vehicle Recorded As DVLA SCRAPPED MARKER On Condition Alert Registr. WARNING LIGHTS ON DASH*
SLIDING 5TH WHEEL

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Air conditioning

Photos





