

VEHICLE INSPECTION REPORT

MX19UYV

Ford Ranger WILDTRAK 3.2 TDCI 200PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/03/2019

Year 2019

Mileage 149,228 Miles
Warranted

Fuel Type Diesel

Colour BLACK

VIN 6FPPXXMJ2PJR39088

Body Style Pickup Double Cab

MOT Due 28/03/2026

CAP Clean £6,300.00

CAP Average £5,525.00

CAP Below £4,400.00

Gearbox MANUAL

Gears 6

Axle Combi 4x4

AD-BLUE, E/ MIRRORS, HEATED WINDSCREEN

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Navigation system
- Digital radio
- Drivers airbag
- Cruise control
- Park assist camera
- Air conditioning
- Passenger airbag
- Front parking sensor
- Rear parking sensor
- Front electric windows
- Central locking
- Heated front seat
- Auxiliary input socket
- Rear electric windows
- Leather seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



4: Tailgate
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door osr
Scratched
Over 25mm Thru Paint



9: Wheel osf
Scratched
Over 50mm



10: Bumper Front
Scratched
Over 100mm Thru Paint



11: Screen Front
Chipped
Over 10mm



12: Fascia Panel
Missing
Replace



13: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs		OK	No Excessive Smoking
			OK
EML light illuminated		OK	DPF light illuminated
			OK
ABS light illuminated		OK	