

VEHICLE INSPECTION REPORT

Vehicle

FN72ZNE

Iveco Daily 35-140 2.3 3450 WB

Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	07/09/2022	VIN	ZCFCP35A90D714593	CAP Below	£5,225.00
Year	2022	Body Style	Dropside	Gearbox	MANUAL
Mileage	177,371 Miles Warranted	MOT Due	06/09/2026	Gears	6
		CAP Clean	£6,600.00		
Fuel Type	Diesel	CAP Average	£6,050.00		
Colour	SILVER				

WARNING LIGHT ON DASH AD-BLUE, E/ MIRRORS

ı	у	ľ	е	S

Inspection

NSF

NSR

OSF

OSR Spare

Features

- Bluetooth connection
- Front electric windowsCloth seat trim
- Cruise controlDrivers airbag
- Digital radio
- Passenger airbag
- · Air conditioning
- Central locking

Photos



















Condition Check



Damage Photos




1: Bonnet Chipped Multiple Chips



2: Panel Front Chipped Multiple Chips



3: Door Mirror Assy nsf Broken Replace



4: Door nsf Chipped Multiple Chips



5: Door Mirror Assy osf Broken Replace



6: Door osf Chipped Multiple Chips



7: B Post os Scratched Over 25mm Thru Paint



8: Screen Front Chipped Over 10mm

Interior

Carpet Condition	OK	Upholstery Condi		
Seat Condition Engine Runs	OK	Odour OK No Excessive Sn	No	OK
Engine Runs		ON NO Excessive Sil	noking	OK
EML light illuminated		OK DPF light illumina	DPF light illuminated	
ABS light illuminated		ОК		