

VEHICLE INSPECTION REPORT

KJ19TRX

SCANIA S 500

Inspection

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/05/2019	Colour	BLACK	Gearbox	AUTOMATIC
Year	2019	VIN	YS2S6X20009257405	Axle Combi	6x2
Mileage	702,107 Km Not Warranted	Body Style	Tractor (Heavy Haulage)	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	HIGHLINE CAB		

REAR LIFT, SLIDING 5TH WHEEL, TWIN LINE PTO HYDRAULICS, WALKING FLOOR EQUIPMENT FITTED, SERVICED & MAINTAINED BY SCANIA

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Navigation system
- Air conditioning
- Leather seat trim