

# VEHICLE INSPECTION REPORT

**C355300**

## DON BUR BOX

### Inspection

### Vehicle

VAT	Plus VAT
V5	N/A

### Details

Reg. date	01/01/2013	Colour		Brakes	Drum
Year	2013	VIN	SEPBV38GKDL061799	Axle Combi	Tri
Mileage	Not Showing	Body Style	Trailer	Rear Suspension	Air
Fuel Type		MOT Due	30/06/2026	Rear Doors	Roller

\*CORROSION\* BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos









