

VEHICLE INSPECTION REPORT



Fiat Ducato Maxi 42 Multijet 2

Inspection		Vehicle		
Serious Damage?	No	VAT	Plus VAT	
		V5	Buyer To Apply	


Details					
Reg. date	19/07/2018	Colour	White	CAP Clean	£4,550.00
Year	2018	VIN	ZFA25000002G99512	CAP Average	£3,925.00
Mileage	123,849 Miles Not Warranted	Body Style	Welfare Bus	CAP Below	£3,050.00
		MOT Due	12/01/2026	Gearbox	MANUAL
Fuel Type	Diesel				

A/C, SIDE LOADING DOOR, E/WINDOWS, REAR VIEW CAMERA, REAR WHEELCHAIR LIFT


Tyres		
Tyres NSF		
NSR		
OSF		
OSR		
Spare	·	

Photos





Condition Check



Damage Photos



1: Qtr Panel osr Scratched UpTo 25mm Thru Paint

Interior

Carpet Condition Seat Condition

2: Roof Scratched UpTo 25mm Thru Paint

Upholstery Condition Odour