

VEHICLE INSPECTION REPORT

DK71PXJ

Isuzu N75 190

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 22/09/2021

Year 2021

Mileage 176,770 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN JAANPR75MK7100901

Body Style Dropside

MOT Due 31/07/2026

Cab Type DAY CAB

Gearbox AUTO

Axle Combi 4x2

Rear Suspension Steel

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Radio/CD
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Auxiliary input socket
- Front electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bumper Rear
Dented
Over 30mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		