

VEHICLE INSPECTION REPORT

VU68FYL

FORD TRANSIT CONNECT 220 1.5 ECOBLUE 120PS

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	19/09/2018	VIN	WF04XXWPG4JM08574	CAP Below	£2,825.00
Year	2018	Body Style	Crew Van L1	Gearbox	MANUAL
Mileage	91,301 Miles Not Warranted	MOT Due	19/02/2026	Gears	6
		CAP Clean	£4,200.00		
Fuel Type	Diesel	CAP Average	£3,625.00		
Colour	WHITE		·		

^{*}WARNING LIGHT ON DASH* AD-BLUE, SIDE LOAD DOOR

ı	уr	es
_		_

NSF

NSR

OSF

OSR Spare

Features

- Bluetooth connection
- Passenger airbag
- · Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

· Drivers airbag

Photos
















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Door Mirror Assy nsf Scuffed (Unpainted) Over 100mm



3: Screen Front Chipped Over 10mm



4: Seat Base Cover nsr Soiled Heavy



5: Seat Back Cover nsr Soiled Heavy



6: Seat Base Cover nsr Soiled Heavy



7: Seat Back Cover nsr Soiled Heavy



8: Seat Back Cover osr Soiled Heavy



9: Seat Base Cover osr Soiled Heavy



10: Seat Base Cover osf Soiled Heavy



11: Seat Back Cover osf Soiled Heavy



12: Seat Back Cover nsf Soiled Heavy



13: Seat Base Cover nsf Soiled Heavy



14: Dash Warning Lights Displayed No Action

Interior

Carpet Condition Seat Condition	OK Poor		Upholstery Condition Odour	OK Yes	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		Fault
ABS light illuminated		OK			