

VEHICLE INSPECTION REPORT

EB19BXV

FORD TRANSIT CUSTOM 300 2.0 ECOBLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/08/2019

Year 2019

Mileage 71,183 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0ZXXTTGZJG86578

Body Style Crew Van L1

MOT Due Expired

CAP Clean £11,100.00

CAP Average £9,750.00

CAP Below £7,775.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS, HEATED WINDSCREEN, DEADLOCKS (WITH KEYS)

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Heated front seat
- Air conditioning
- Central locking


Photos








Condition Check



Damage Photos



1: Roof
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Wheel nsr
Scratched
Over 50mm



4: Wheel osr
Scratched
Over 50mm



5: Seat Base Cover nsr
Soiled
Heavy



6: Seat Base Cover osr
Soiled
Heavy



7: Seat Base Cover osf
Burn
Over 3mm



8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
Airbag light illuminated	Fault		
ABS light illuminated	Fault		