

VEHICLE INSPECTION REPORT

SJ66SYH

Fiat Ducato 42 2.3 Multijet 180PS

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Present

Details

Reg. date	18/01/2017	Colour	RED	CAP Average	£4,325.00
Year	2017	VIN	ZFA25000002C98994	CAP Below	£3,300.00
Mileage	82,671 Miles Not Warranted	Body Style	Minibus	Gearbox	SEMI AUTO
Fuel Type	Diesel	CAP Clean	£5,100.00		

NON RUNNER-CRANKS BUT WILL NOT FIRE *WARNING LIGHTS ON DASH* A/C, SIDE LOADING DOOR, E/MIRRORS

Tyres



NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Rear
Insecure
Action Required



2: Door Mirror Assy nsf
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Mechanical Inspection

Important Notice: Customer must satisfy themselves that the health check is as stated by 5pm day after sale and prior to leaving centre. If vehicle has been delivered we must be notified within two hours of arrival at your dealership.

Engine Runs	Fault
EML light illuminated	Fault
ABS light illuminated	Fault