

VEHICLE INSPECTION REPORT

SF66VNN

Citroen Berlingo 625 1.6 BlueHDi 75ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/09/2016

Year 2016

Mileage 76,831 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF77BBHW6GJ760805

Body Style Panel Van L1

MOT Due 18/09/2026

CAP Clean £2,700.00

CAP Average £2,225.00

CAP Below £1,650.00

Gearbox MANUAL

Gears 5

Axle Combi 4x2

SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Not Thru Paint



3: Bumper Rear
Poor Previous Repair
Rippled UpTo 30%

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		