

VEHICLE INSPECTION REPORT

SF66VNU

Citroen Berlingo 625 Enterprise 1.6 BlueHDi 75ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 12/09/2016

Year 2016

Mileage 89,124 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF77BBHW6GJ760817

Body Style Panel Van SWB

Keys 1

MOT Due 20/10/2025

CAP Clean £2,525.00

CAP Average £2,075.00

CAP Below £1,550.00

Gearbox MANUAL

Gears 5

Axle Combi 4x2

AD BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Drivers airbag
- Radio/CD
- Central locking
- Air conditioning
- Cloth seat trim
- Front electric windows

Photos





Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm



2: Bonnet
Rusted
Over 5mm



3: Bumper Front
Insecure
Action Required



4: Door osf
Dented
With Paint Damage



5: Qtr Panel osr
Dented
Over 30mm



6: Tailgate
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
Over 30mm



8: Door osf
Dented
Over 30mm



9: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK