

VEHICLE INSPECTION REPORT

YK68WKO

Volvo FH 500

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/11/2018

Year 2018

Mileage 810,047 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN YV2RT40CXKB883277

Body Style Tractor Unit

MOT Due 30/11/2025

Cab Type GLOBETROTTER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

*MILEAGE DISCREPANCY ON MOT**LARGE CRACK IN WINDSCREEN* TWIN FUEL TANKS, SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio
- Central locking
- Navigation system
- Air conditioning
- Cloth seat trim
- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Panel Front
Dented
With Paint Damage



4: Bumper Front
Dented
With Paint Damage



5: Bumper Front Moulding
Broken
Replace



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel Trim nsf
Broken
Replace



8: Door osf
Dented
With Paint Damage



9: Door osf
Dented
With Paint Damage



10: Screen Front
Cracked
Replace



11: Door Pad osf
Soiled
Heavy



12: Seat Base Cover osf
Burn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		