

VEHICLE INSPECTION REPORT

PE17HSA

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 14/03/2017

Year 2017

Mileage 1,580,140 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G150431

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due 31/12/2025

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

COLLECTED AS NON RUNNER - CORROSION

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel Moulding ns
Missing
Replace



5: Qtr Panel Moulding os
Missing
Replace



6: Panel Rear
Dented
With Paint Damage



7: Door osf
Scratched
Over 25mm Not Thru Paint



8: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		