

VEHICLE INSPECTION REPORT

PO13DZT

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	03/04/2013	VIN	XLRAE45FF0L425174	Cab Type	DAY CAB
Year	2013	Body Style	Box Van	Gearbox	MANUAL
Mileage	830,563 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	28/02/2026	Tail Lift	Cantilever

*COLLECTED AS NON RUNNER - TURBO ISSUES**WARNING LIGHT ON DASH*

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osf
Dented
With Paint Damage



5: Screen Front
Chipped
Over 10mm



6: Door Pad osf
Soiled
Heavy



7: Carpets Front
Torn
Over 10mm



8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		