

VEHICLE INSPECTION REPORT

PN19HNT

Volvo FH 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/03/2019

Year 2019

Mileage 611,852 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN YV2RTY0CXKB902109

Body Style Tractor Unit

MOT Due 30/09/2025

Cab Type GLOBETROTTER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

SLIDING 5TH WHEEL

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Air conditioning
- Partial leather seat trim
- Front parking sensor
- Front electric windows
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Door nsf
Scratched
Over 25mm Thru Paint



2: Door nsf
Scratched
Over 25mm Thru Paint



3: Panel Front
Scratched
Over 25mm Thru Paint



4: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



5: Panel Front
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition OK

Upholstery Condition Average
Odour -