

VEHICLE INSPECTION REPORT

C300568

DON-BUR FRIDGE BOX DOUBLE DECK

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2011	Colour	WHITE	Brakes	Drum
Year	2011	VIN	SEPBV39ANBI057149	Axle Combi	Tri
Mileage	Not Showing	Body Style	Trailer	Rear Suspension	Air
Fuel Type		MOT Due	Expired	Rear Doors	Barn

BPW AXLES, RAISE AND LOWER VALVE

Tyres

NSF
NSR
OSF
OSR
Spare