

VEHICLE INSPECTION REPORT

LN64CNY

Mercedes-Benz Econic 2630

Non Runner

Inspection

Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details


Reg. date	28/01/2015	Colour	WHITE	Cab Type	CREW CAB
Year	2015	VIN	WDB9560632V238078	Gearbox	AUTOMATIC
Mileage	Not Showing	Body Style	Refuse Collector	Axle Combi	6x2
Fuel Type	Diesel	MOT Due	30/04/2026	Rear Suspension	Steel


NON RUNNER - PARTIALLY STRIPPED, DOES NOT POWER UP FAUN VARIOPRESS BODY, SINGLE LIFT, LAST KNOWN MOT MILEAGE 370,735KM 13/03/2025

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Flasher Side Repeater os
Broken
Replace



2: Bumper Front Moulding
Broken
Replace



3: Bonnet
Missing
Replace



4: Number Plate Front
Missing
Replace



5: Flasher Side Repeater ns
Broken
Replace



6: Bumper Front Moulding
Broken
Replace



7: Other
N/A
N/A



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Wheel nsf
Missing
Replace



11: Wheel nsr
Missing
Replace



12: Wheel nsr
Missing
Replace



13: Other
N/A
N/A



14: Wheel nsr
Missing
Replace



15: Wheel nsr
Missing
Replace



16: Other
N/A
N/A



17: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



18: Wheel osr
Missing
Replace



19: Wheel osr
Missing
Replace



20: Wheel osr
Missing
Replace



21: Wheel osr
Missing
Replace



22: Wheel osr
Missing
Replace



23: Wheel osr
Missing
Replace



24: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



25: Door Mirror Glass os
Missing
Replace



26: Other
N/A
N/A



27: Other
N/A
N/A



28: Other
N/A
N/A



29: Other
N/A
N/A



30: Other
N/A
N/A



31: Other
N/A
N/A

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs		Fault	