

VEHICLE INSPECTION REPORT

PE65UZZ

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	16/10/2015	VIN	XLRAEL3700L448282	Cab Type	DAY CAB
Year	2015	Body Style	Box Van	Gearbox	AUTOMATIC
Mileage	746,798 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	31/05/2026	Tail Lift	Cantilever

*COLLECTED AS NON RUNNER - GEARBOX/ CLUTCH ISSUES**WARNING LIGHT ON DASH*


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Number Plate Front
Missing
Replace



3: Bumper Front
Dented
With Paint Damage



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Door Pad osf
Soiled
Heavy



6: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		