

# VEHICLE INSPECTION REPORT

**SA60DNE**

## Volkswagen Transporter T30 2.0 TDI 84PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 27/01/2011

Year 2011

Mileage 142,795 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WV1ZZZ7HZBH070995

Body Style Panel Van LWB

Keys 2

MOT Due 28/01/2026

CAP Clean £4,425.00

CAP Average £3,425.00

CAP Below £2,250.00

Gearbox MANUAL

Gears 5

Axle Combi 4x2

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

## Condition Check



## Damage Photos



1: Sill os  
Rusted  
Over 5mm



2: Bonnet  
Rusted  
Over 5mm



3: Bumper Front  
Insecure  
Action Required



4: Door osf  
Rusted  
Over 5mm



5: Qtr Panel osr  
Rusted  
Over 5mm



6: Tailgate  
Dented  
Over 30mm



7: Door nsr  
Dented  
Over 30mm



8: Door nsf  
Dented  
Over 30mm



9: Wing nsf  
Dented  
Over 30mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK