

VEHICLE INSPECTION REPORT

BX71DPN

ISUZU D-MAX 1.9 V-Cross

Inspection

Vehicle

| | |
|-----|----------|
| VAT | Plus VAT |
| V5 | Present |

Details

| | | | | | |
|-----------|----------------------------|-------------|-------------------|------------|------------|
| Reg. date | 13/09/2021 | VIN | MPATFS87JMT007105 | CAP Below | £11,250.00 |
| Year | 2021 | Body Style | Pickup Double Cab | Gearbox | AUTOMATIC |
| Mileage | 109,042 Miles Warranted | MOT Due | 12/09/2026 | Gears | 6 |
| Fuel Type | Diesel | CAP Clean | £14,700.00 | Axle Combi | 4x4 |
| Colour | WHITE | CAP Average | £13,400.00 | | |

E/MIRRORS

Tyres

| |
|-------|
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Features

- Front parking sensor
- Front electric windows
- Park assist camera
- Rear electric windows
- Rear parking sensor
- Leather seat trim
- Air conditioning