

# VEHICLE INSPECTION REPORT

**YN68YDV**

## SCANIA R 450

**Non Runner**  
Inspection

<b>Serious Damage?</b>	No	<b>Vehicle</b>	
		<b>VAT</b>	Plus VAT
		<b>V5</b>	Buyer To Apply

### Details

<b>Reg. date</b>	29/11/2018	<b>VIN</b>	YS2R6X20005528355	<b>Axle Combi</b>	6x2
<b>Year</b>	2018	<b>Body Style</b>	Tractor Unit	<b>Steering Combi</b>	Mid-Lift
<b>Mileage</b>	367,294 Km Not Warranted	<b>MOT Due</b>	31/12/2025	<b>Rear Suspension</b>	Air
<b>Fuel Type</b>	Diesel	<b>Cab Type</b>	SLEEPER CAB		
<b>Colour</b>	WHITE	<b>Gearbox</b>	AUTOMATIC		

\*NON RUNNER - ONLY DRIVES IN REVERSE\*\*WARNING LIGHT ON DASH\* SINGLE LINE PTO HYDRAULICS, SLIDING 5TH WHEEL

### Tyres

<b>NSF</b>	<b>NSI1</b>	<b>NSI2</b>	<b>NSI3</b>	<b>NSI4</b>
<b>OSF</b>	<b>OSI1</b>	<b>OSI2</b>	<b>OSI3</b>	<b>OSI4</b>
<b>Spare</b>	<b>NSO1</b>	<b>NSO2</b>	<b>NSO3</b>	<b>NSO4</b>
	<b>OSO1</b>	<b>OSO2</b>	<b>OSO3</b>	<b>OSO4</b>


## Features

- Bluetooth connection
- Mobile phone App interface
- Front electric windows
- Cruise control
- USB/iPod interface
- Drivers airbag
- Park assist camera
- Manual sunroof
- Central locking
- Digital radio
- Air conditioning
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Fuel Flap  
Missing  
Replace



2: Panel Front  
Scratched  
Over 25mm Not Thru Paint



3: Bumper Front  
Missing  
Replace



4: Bumper Front  
Missing  
Replace

**Interior**

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	-

**Mechanical Inspection**

**Important Notice: Customer must satisfy themselves that the health check is as stated by 5pm day after sale and prior to leaving centre. If vehicle has been delivered we must be notified within two hours of arrival at your dealership.**