

VEHICLE INSPECTION REPORT

LN67WRJ

Ford Transit 350 2.0 TDCi 130ps H2 Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 30/09/2017

Year 2017

Mileage 171,033 Miles
Warranted

Fuel Type Diesel

Colour GREEN

VIN WF0XXXTTGXHB70937

Body Style Panel Van L3

MOT Due 29/09/2026

CAP Clean £2,925.00

CAP Average £2,500.00

CAP Below £1,875.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, TOW BAR, DEADLOCKS (WITH KEY)

Tyres

NSF

NSR

OSF

OSR




Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Other
N/A
N/A



3: Qtr Panel nsr
Dented
Over 30mm



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage



8: Wing osf
Dented
Over 30% Of Panel



9: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		